


TWO ASPECT SIGNALS with stop block for automation



GAP - air space between rails, a plastic insulator may be used.

All TRAK-DT's need to be connected to the 12VPS "+" and "-" accordingly for proper operating power.